





PURE+FREEFORM

www.purefreeform.com info@purefreeform.com
612-208-8347




MP-10 PERFORATION

.043" ROUND HOLES @
.240" STRAIGHT CENTERS
(2.5% OPEN)




MP-11 PERFORATION

.043" ROUND HOLES @
.170" DIAGONAL CENTERS
(5% OPEN)



MP-12 PERFORATION

.063 ROUND @
.238 STRAIGHT CENTERS
(5% OPEN)



MP-13 PERFORATION


.063 ROUND @
.168 DIAGONAL CENTERS
(10% OPEN)

MICRO PERFORATIONS




PURE+FREEFORM

www.purefreeform.com info@purefreeform.com
612-208-8347



MP-14 PERFORATION

.063 ROUND @
.320 STRAIGHT CENTERS
(3% OPEN)



MP-15 PERFORATION


.063 ROUND @
.226 DIAGONAL CENTERS
(6% OPEN)

MICRO PERFORATIONS




PURE+FREEFORM

www.purefreeform.com info@purefreeform.com
612-208-8347




SP-16 PERFORATION

.078" DIA. HOLES @ .290"
STRAIGHT CENTERS
(5.5% OPEN)




SP-17 PERFORATION

.078" DIA. HOLES @ .205"
DIAGONAL CENTERS
(11% OPEN)



SP-18 PERFORATION

.078" DIA. HOLES @ .162"
STAGGERED CENTERS
(22% OPEN)



SP-19 PERFORATION


.078" DIA. HOLES @ .145"
STRAIGHT CENTERS
(22% OPEN)

SMALL PERFORATIONS




PURE+FREEFORM

www.purefreeform.com info@purefreeform.com
612-208-8347




SP-20 PERFORATION

3/32" DIA. HOLES @ 3/16"
STRAIGHT CENTERS
(20% OPEN)




SP-21 PERFORATION

3/32" DIA. HOLES @ 3/16"
STAGGERED CENTERS
(23% OPEN)



SP-22 PERFORATION

3/32" DIA. HOLES @ 3/8"
STRAIGHT CENTERS
(5% OPEN)



SP-23 PERFORATION


3/32" DIA. HOLES @ 1/4"
DIAGONAL CENTERS
(10% OPEN)

SMALL PERFORATIONS




PURE+FREEFORM

www.purefreeform.com info@purefreeform.com
612-208-8347




SP-24 PERFORATION

1/8" DIA. HOLES @ 1/4"
STRAIGHT CENTERS
(20% OPEN)




SP-25 PERFORATION

1/8" DIA. HOLES @ 1/4"
STAGGERED CENTERS
(20% OPEN)



SP-26 PERFORATION

1/8" DIA. HOLES @ 1/2"
STRAIGHT CENTERS
(5% OPEN)



SP-27 PERFORATION


1/8" DIA. HOLES @ .354"
DIAGONAL CENTERS
(10% OPEN)

SMALL PERFORATIONS




PURE+FREEFORM

www.purefreeform.com info@purefreeform.com
612-208-8347




LP-40 PERFORATION

3/16" DIA. HOLES @ 3/8"
TRUE STAGGERED CENTERS
(23% OPEN)




LP-41 PERFORATION

3/16" DIA. HOLES @ .65", 3/4"
STRAIGHT CENTERS
(5% OPEN)



LP-42 PERFORATION

3/16" DIA. HOLES @ 3/8"
STRAIGHT CENTERS
(20% OPEN)



LP-43 PERFORATION


3/16" DIA. HOLES @ 1/4"
DIAGONAL CENTERS
(39% OPEN)

LARGE PERFORATIONS




PURE+FREEFORM

www.purefreeform.com info@purefreeform.com
612-208-8347




LP-44 PERFORATION

1/4" DIA. HOLES @ 1/2"
STRAIGHT CENTERS
(20% OPEN)




LP-45 PERFORATION

3/8" DIA. HOLES @ 3/4"
STRAIGHT CENTERS
(20% OPEN)



LP-46 PERFORATION

3/8" DIA. HOLES @ .530"
DIAGONAL CENTERS
(39% OPEN)



LP-47 PERFORATION


3/8" DIA. HOLES @ 1 1/4"
STRAIGHT CENTERS
(7% OPEN)

LARGE PERFORATIONS




PURE+FREEFORM

www.purefreeform.com info@purefreeform.com
612-208-8347




LP-48 PERFORATION

3/8" DIA. HOLES @ 7/8"
DIAGONAL CENTERS
(15% OPEN)




LP-49 PERFORATION

3/8" DIA. HOLES @ 5/8"
STAGGERED CENTERS
(29% OPEN)



LP-50 PERFORATION

1/2" DIA. HOLES @ 1"
STRAIGHT CENTERS
(20% OPEN)



LP-51 PERFORATION


1/2" DIA. HOLES @ .707"
DIAGONAL CENTERS
(39% OPEN)

LARGE PERFORATIONS




PURE+FREEFORM

www.purefreeform.com info@purefreeform.com
612-208-8347



LP-52 PERFORATION

1/2" DIA. HOLES @ 1"
STAGGERED CENTERS
(20% OPEN)



LP-53 PERFORATION


1 1/4" DIA. HOLES @ 2"
STRAIGHT CENTERS
(31% OPEN)

LARGE PERFORATIONS




PURE+FREEFORM

www.purefreeform.com info@purefreeform.com
612-208-8347




SQ-10 PERFORATION

1/4" SQUARE HOLES @
1/2" STRAIGHT CENTERS
(25% OPEN)




RT-01 PERFORATION

1/8" x 1" RECTANGULAR
@ 3/8" x 1 3/16" STRAIGHT
CENTERS (27% OPEN)



RT-02 PERFORATION

1/8" x 1" RECTANGULAR
@ 3/4" x 1 3/16" STRAIGHT
CENTERS (--% OPEN)



RT-03 PERFORATION


1/8" X 1-1/16" RECT.
@ 1/2" X 1-1/2" STRAIGHT
CENTERS (18% OPEN)

SQUARE/ RECTANGULAR PERFORATIONS




PURE+FREEFORM

www.purefreeform.com info@purefreeform.com
612-208-8347




OB-60 PERFORATION

1/8" x 1 1/16" OBROUND
@ 7/16" x 1 5/16" STRAIGHT
CENTERS (23% OPEN)



OB-61 PERFORATION

1/8" x 1 1/16" OBROUND
@ 7/32" x 1 5/16" STRAIGHT
CENTERS (45% OPEN)



OB-62 PERFORATION

1/8" x 1 1/16" OBROUND
@ 7/32" x 21/32" STAGG.
CENTERS (45% OPEN)

OBROUND PERFORATIONS